


CODE	Soil Series	Drainage Class
108	Saco silt loam	Alluvial and floodplain soils
12	Raypol silt loam	Poorly drained soils
18	Catden and Freetown soils	Very poorly drained soils
21A	Ninigret and Tisbury soils, 0 to 5 percent slopes	Moderately well drained
29A	Agawam fine sandy loam, 0 to 3 percent slopes	Well drained
306	Udorthents-Urban land complex	N/A
307	Urban land	N/A
34A	Merrimac sandy loam, 0 to 3 percent slopes	Excessively drained
36B	Windsor loamy sand, 3 to 8 percent slopes	Excessively drained
36C	Windsor loamy sand, 8 to 15 percent slopes	Excessively drained



Legend

- Approx. Limits-of-Work
- Alluvial and Floodplain Soils
- Poorly Drained and Very Poorly Drained Soils
- SSURGO Soils Area

0 500 1,000 2,000
Feet



NRCS Soils

Proposed Distribution Facility Site
35 Bacon Road, Enfield, CT

SCALE	DATE	PROJECT NO.
1:12,000	11/21	60644518

AZCOM

Figure Number

2